


South Weber 24" Culinary Pipeline Replacement RSOQ Request for Information Response

Date: 13 November 2017

Subject: RSOQ RFI Responses #1

Below is a list of responses to RFIs that have been received regarding the South Weber pipeline replacement project:

1. What is the nature of the replacement of ductile iron pipe being installed in 1981? That is not a very old pipe.
 - The pipe has extensive corrosion and has been causing a lot of maintenance issues.
2. The existing pipeline shows problems and needs to be replaced. Is the line leaking or bad soil conditions corroding due to the plume from Hill Air Force Base, or what are the problems the line is experiencing? I'm assuming the district does not want to line the existing pipe, is that correct?
 - Correct, we do not want to line the existing pipe. The corrosion is too extensive to the existing pipe to justify lining it. The line has had a few leaks caused by corrosion. We do not know of any correlation with the HAFB plume.
3. Does the district want to replace the pipe with same size line or does it need to be upsized?
 - The line will likely remain the same size.
4. Has the district considered as an alternative to replacement to pipe burst the existing pipe? There are some bends that may make it cost prohibitive? We could bid it with two different Alternatives.
 - This is a request for qualifications only, no bids should be submitted at this time. Pipe bursting is an alternative we would like to consider with the assistance of the design firm we select.
5. Does the district favor HDPE pipe, or fusible polyvinylchloride (FPVCP) pipe or other desired type of pipe?
 - We do not favor fused PVC. All options, however, would be considered with the assistance of the firm that is selected.
6. Are there services and fire hydrants on this pipeline?
 - There are no services or hydrants connected to this line.
7. The projects states that 200 feet of section of pipe was replaced last year. Was this ductile iron pipe?
 - The existing pipe was ductile iron and was replaced with C900.



South Weber 24" Culinary Pipeline Replacement RSOQ Request for Information Response

8. Does this pipeline need to remain in service with its replacement or can it be taken out of service during construction time?
 - The pipeline will need to be taken out of service.
9. What time of year does the district want to replace this line? This will impact Schneiters Riverside Golf Course
 - Construction will ideally be during low demand season, likely fall of 2018.